

# 通知

## Announcement

感謝您對 Epson 商品的支持與愛護。

若您有使用吊掛式安裝、壁掛式安裝、板架安裝於油煙環境中（例如：多油煙烹飪場所、多油污工廠）的投影機，因吊掛式安裝的投影機外殼及支架固定部位，受散佈於空氣中的大量油煙附著後，可能造成支架固定部位的塑料變質造成投影機掉落。

Epson 長期致力於顧客權益維護及提供最優質的服務，本公司將為使用者進行投影機吊架強化之安裝施作。請您透過 Epson 洽詢專線：[\(02\)8024-2008](tel:0280242008)，或藉由服務信箱：[public.affairs@exc.epson.com.tw](mailto:public.affairs@exc.epson.com.tw)，與我們聯繫。

本公司再次感謝您的配合，若因此造成您的不便，懇請見諒。

Thank you for your support to Epson products,

We would like to make a notice that under the circumstances of oily fume environment (such as kitchen area with heavy smoke or soot factory), our projectors, which including ceiling mounts, wall mounts and projector stands has the possibility to drop, due to fragile bracket plastic caused by the deterioration.

Epson take your needs as our major priority and contribute ourselves to premium services for our customers. We will start our projector enforcement services for your needs, please feel free to contact us via our Hotline or Email as below.

Hotline : [\(02\)8024-2008](tel:0280242008) / Email : [public.affairs@exc.epson.com.tw](mailto:public.affairs@exc.epson.com.tw)

Thank you for your understanding, we apologize for any inconvenience caused.

台灣愛普生科技股份有限公司

Epson Taiwan Technology & Trading Ltd.

2019 年 3 月 26 日